

David Kelly's report was as follows:

The Horstmann control unit was wired incorrectly since fitting. The unit had two supplies when only fit for one. The Immersion 1 off peak (base heating unit) was connected via a link to the Immersion 2 peak heating unit as shown in the image. This has likely caused a continued overload of Immersion 1.


The electronic display and control unit is designed to run off the supply of one switch with an insitu boost switch to operate the second immersion heater if needed to boost hot water supply. This was not how the product in Apartment 8 was wired.

Wiring corrected and switch tested to 20amp fuse tolerance.

IMMERSION 1



thager



WARNING
THIS UNIT
MUST BE
EARTHED

H.V.
0/1

H.V.

QC OK
5017

RoHS
COMPLIANT

HOTTOLMANN
ELECTRONIC 7
SERIES III
13A 230V
50Hz ~ T95
CE
RoHS
COMPLIANT
QC OK 5017
HOTTOLMANN LTD LK BRISTOL, G4 7LP
www.hottolmann.co.uk

